Ruins of Windsor Castle Near Port Gibson, Miss. H.A.B.S. No. Miss. 26

HABS

MISS.

II-Posic.v

.

PHOTOGRAPHS WRITTEN HISTORICAL AND DESCRIPTOVE DATA DISTRICT OF MISSISSIPPI

Historic American Buildings Survey A. Hays Town, District Officer Jackson, Miss.

Page 1 HAES

WINDSOR CASTLE (RUINS)
Port Sibson, Claiborne County, Mississippi

11. Postkiv

Owner. (Or Custodian)

Mrs. J. M. Magruder

1973 STATE OF MISSISSIPPI

Date of Erection

1860

Architect

Builder

S.C. Daniel (Large plantation owner)

Present Condition

Ruins

BURNED 1891

*Number of Stories

Materials of Construction

Foundation

Ploors

Exterior Walls

Interior Walls

Roof

Other Existing Records

Brick columns stucceed with stucceed brick pedeetals and bases and east iron Corinthian Capitals. Large galleries surrounded the house completely with lacelike east iron railings. The stucce work was particularly well executed, very much more refined than the early examples.

Additional Data

Windsor Caetle is almost a complete ruin, but sufficient details still remain to afford an imaginary picture of the original house. Slave labor was used throughout the construction of the house.

The the